



*Var.*

for <sup>my</sup> M Parker Dep

Course.	Point of Beginning.	Chains Distance.	Corrected Bearings.
East	NW 4	51.13	division Stone
		63.77	" "
		80.51	NE 4-7-4
North	SE 4	5.00	to bank of Richland Creek which meanders along line a considerable
		20.00	(Stone & Redgum)
		64.00	" " " " " course west
		81.09	NE
West	E 7/4	12.50	Richland Creek
		40.00	center
North		5.00	beginning 23,50 ch East of center thence
		12.00	North bank of Creek course SE
		41.78	Richland Creek course S 80 W
		22.25	Stone on sec line thence
South		6.50	
East			

I noticed in this survey that the dist. on N side of the section did not correspond with dist. I had reported or rather noted <sup>in</sup> a former survey. The difference being uncommon. I then noticed the chain carriers closely but found no reason for the discrepancy. I use a two rod Gunter's chain and after returning home found the chain too long. The chain is much worn and I measured it frequently and cannot conceive how it happened unless something happened in my absence. The measure however corresponds very well with the good record on East line. So the corner set on E line of section may be said to be in ratio with government measurements.